

Message Text

LIMITED OFFICIAL USE

PAGE 01 KUALA 09276 280948Z
ACTION SY-05

INFO OCT-01 EA-10 ISO-00 STE-01 /017 W
-----124425 281249Z /47

R 280855Z AUG 78
FM AMEMBASSY KUALA LUMPUR
TO AMEMBASSY BANGKOK
INFO AMCONSUL HONG KONG
AMEMBASSY MANILA
SECSTATE WASHDC 7924

LIMITED OFFICIAL USE KUALA LUMPUR 9276

BANGKOK AND MANILA FOR TSO

HONG KONG FOR RTC

DEPT FOR SY/OPS/T

E.O.11652: N/A
TAGS: ASEC
SUBJECT: CCTV'S - KUALA LUMPUR

1. FOR TSO-KUALA LUMPUR HAS NEED OF 1 TV MONITOR PLUS 1 CAMERA.
RSO HAS LENS.

2. RESISTOR FOR ASC 630 RECEIVED AND INSTALLED. IT WORKS.

3. WE SEEM TO BE EXPERIENCING A HEAT DISSIPATION PROBLEM WITH THE
MONITORS INSTALLED IN THE DESK. HAS THIS BEEN MENTIONED PREVIOUSLY?

4. FOR ST/T - CONTACTED CHUBB IN KUALA LUMPUR REGARDING POSSIBILITY
OF SERVICING CONCORD CAMERAS LOCALLY. THEY HAVE TECHNICAL
CAPABILITY TO SERVICE, BUT NO CONCORD PARTS (CIRCUIT BOARDS, ETC).
A POSSIBLE ARRANGEMENT WAS DISCUSSED WITH CHUBB REPRESENTATIVE
WHEREBY CHUBB WOULD TAKE THE CAMERA AND ASCERTAIN THE DEFECTIVE PART.

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 KUALA 09276 280948Z

CHUBB WOULD PASS THAT INFORMATION TO RSO FOR RELAY TO SY. CHUBB
WOULD THEN INSTALL THE NEW PART ON ARRIVAL. FYI -THIS PLAN WAS
DEVELOPED BECAUSE OF THE LONG DELAYS CHUBB HAS EXPERIENCED IN GETTING
PARTS FROM THE U.S.

5. BEFORE RSO GOES FURTHER, SEVERAL QUESTIONS NEED ANSWERS:
A. DOES SY HAVE ANY OBJECTION TO THE CONCEPT?

B. DOES SY MAINTAIN A STOCK OF CAMERA PARTS AND/OR IS THE
DELIVERY TIME OF FACTORY PARTS TO SY TWO MONTHS OR LESS?
C. SINCE CAMERA IS SY SUPPLIED, WOULD THE REPAIR BILL BE POST
OR SY RESPONSIBILITY FOR PAYMENT?

6. DECONTROL ON RECEIPT.
MILLER

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 28 aug 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978KUALA09276
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780350-1331
Format: TEL
From: KUALA LUMPUR
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780818/aaaaaovt.tel
Line Count: 69
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: c91cf25a-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 11 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1604447
Secure: OPEN
Status: NATIVE
Subject: CCTV'S - KUALA LUMPUR
TAGS: ASEC
To: BANGKOK
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/c91cf25a-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014